

Date

01-Mar-2020

STRUCTURAL & BUILDING SAFETY

Bangladesh Accord Remediation Summary of Actions Required

Factory Name & Address	Genesis Fashions Ltd. (new unit), 126/1 Kadda Nandun, Kadda Bazar, Gazipur Sadar, Gazipur, Dhaka, Dhaka
Date of Inspection by Accord	24-Oct-2015
Accord Rating	
Finance Plan Agreed	Yes

Visit Type	Sub Visit Type	Item No	Accord Inspection Observation	Accord Action Plan	Final Action Plan	Final Timeline	Comments from Accord	Accord Timeline	Progress Status
Initial Inspection		1	Tighten loose bolts.	Check the connections and tighten loose bolts.	Done. Tthe loose bolts have been tightened and the connections have been checked on 16-11-2015	Nov 23 2015	On 05/01/2017: Loose bolts have been tighten. On 30/05/2017:F ound corrected from nprevious	6-months	Corrected
Initial Inspection		2	Repair corrosion protection paint.	Check structural elements paints and repair corrosion protection paint.	Done. The structural elements paints have been checked corrosion protection paint	Nov 23 2015	On 05/01/2017: Corroded area has been repaired. Factory requires to monitor this in regular basis.	6-months	Corrected
Initial Inspection		3	Verify lateral stability of the parapet wall.	Building Engineer should check parapet wall stability.	Done. Parapet wall stability report is accepted by Accord. The retrofitting work is completed in consultation with	Nov 23 2015	On 05/01/2017: Stability Assessment Report of the factory was accepted on 15th May 2016 in	6-months	Corrected